



TURKEY SPAIN BASE MAINTENANCE CONTRACT

Program Status Review 3rd Qtr – FY14

23 July 2014

1



Significant Events BCE - Spain



- CE Pavements and Repair team received training on Infrared Asphalt Machine and immediately after training responded to an emergency job order for loose asphalt (FOD) on runway.
- Team responded urgently and repaired the asphalt in 1 hour. Normally a job that would have taken several hours. The Infrared Asphalt Machine is paying immediate dividends. Machine will expedite and enhance CE ability to repair base pavements.



2